

г

240 OLD COUNTRY ROAD MINEOLA, N.Y. 11501



FRANCIS T. PURCELL County Executive

JOHN J. DOWLING, M.D., M.P.H. Commissioner

FRANCIS V. PADAR, P.E. Asst. Deputy Commissioner Div. of Environmental Quality

November 14, 1979

Mr. Ernest Schmalz Environmental Protection Agency 26 Federal Plaza Room 812 New York, New York 10007

Re: Cerro Wire - North Side of Plant

Dear Mr. Schmalz:

Pursuant to our telephone conversation on November 13, 1979, I have enclosed the following regarding Cerro Wire:

- 1. Undated memo re inspection of Cerro Wire on 5/22/79.
- 2. Sampling data resulting from above inspection (4 sheets).
- 3. A reinspection report of Cerro Wire on 10/3/79.

In addition, please be advised that public sewers are available and the necessary permits have been applied for by Cerro Wire. To date, they have not been connected.

If there is any further information we can provide, please contact us.

Very truly yours,

Stanley Juczak, Jr., P.E.

Director

Bureau of Land Resources

Management

SJ:ms

Encl.



NASSAU COUNTY DEPARTMENT OF HEALTH

240 Old Country Road

Mineola, New York 11501

To : L. Sama

Date:

From

: J. Schechter, H. Schaefer

Subject:

Inspection of Cerro Wire & Cable Co.

Robbins Lare

Syosset, N.Y.

SPDES NY 0076171

On 5/22/79 at 1:00 A.M., an inspection was conducted at Cerro Wire & Cable Co. Those attending included:

Donald Furst, Plant Manager, Cerro Wire Fred Sarino, Chem. Eng., Cerro Wire

N. Latten, Chief Engineer, Cerro Wire

H. Schaefer, Bureau of Land Resources Mgt., NCDH

J. Schechter, BWWM, NCDH

The inspection was conducted at the request of Stan Juczak for the purposes of verifying and identifying sources of chemical, oil and sanitary waste contamination and spillage on the site.

The inspection revealed the following:

- 1. Numerous drums (55 gallon) are being stored on wooden pallets on a concrete apron on the west side of the property bordered by LIRR on the west and Robbins Lane on the south. The drums were identified as containing the following products.
 - a. Scrap metal including Zn metal from Zinc anodes in open 55 gallon drums.
 - b. Spent coolant water soluble oil many in open top 55 gallon drums.
 - c. Waste oils labelled used oil some in open top drums.
 - d. Spent acids drums labelled "Hot Stuff" identified as containing Znanode and H₂SO_A - closed drums.
 - e. Spent solvent labelled solvent in sealed drums and identified by N. Latten as Solva/Sol (diethylene glycol ethyl ether Mol. Formula $0_3C_6H_{14}$)
- 2. Black metallic particles with the appearance of sludge was noted on a concrete apron to the west of the drums containing acid was identified by N. Latten as copper oxide removed from the hot rolling dies and placed at this location to dry.



Some of the sludge had washed off the concrete and onto the soil. A sample (JS-2-79) of this soil was obtained for analysis. Black streaks in the soil south of the copper oxide drying area were noted and appeared to be runoff from the oxides.

3. Spillage of black oily sludge like material was noted beneath the waste drum pallets on the soil adjacent to the drum storage area. N. Latten stated it was oil spillage, not chemical.

One drum of spent acid was noted leaking onto the concrete pad.

A sample of oily soil was obtained from the soil west and adjacent to the spent coolant (oil). (#JS-04-79)

- 4. Overflowing cesspools were noted in the southwest corner of the property.

 A sample was obtained for analysis (JS-03-79)

 Evidence indicates sanitary system cannot handle flow.
- 5. Two illegal discharges noted north of the boiler building One identified by Donald Furst as boiler blowdown, the other as possibly compressor cooling water. The boiler blowdown water was brown in coloration.
- 6. A pit containing oil soaked sand was noted north of the boiler building along the property line.
- A ditch was noted north of the copper oxide drying area.
 A pipe was noted at the eastern end of the ditch. The bottom of the ditch contained water and the bottom and side walls were discolored. Mr. Latten indicated that the pipe discharged storm water runoff from storm drains to the east of this area. Dye testing of storm drains verified this fact. Mr. Latten stated that the pipe had been constructed due to collapse of the storm water catch basins.

A sample of water at the bottom of the ditch was obtained for bacterial and chemical analysis (JS-01-79).

8. Staining of soil adjacent to drum storage area noted.

Mr. Latten was advised that contaminated soil would have to be removed from the area and disposed by an industrial waste scavenger. He was also advised that the boiler blowdown discharge was not covered by the SPDES Permit NY 0076171.

Mr. Latten stated that the waste oil would be burned in the boiler and waste acids would be treated in the plant after analysis by Mr. Marino.

Mr. Latten was advised that another inspection would be held along with NYSDEC and NYSDOT representatives to discuss the disposition of spilled oils and chemicals.

(Signed) Joseph Schechter (Signed) Howard Schaefer

ENVIRONMENTAL Owner or Inspector Perro Wire HEALTH Agent Continuation Sheeled -Address: Nassau County Health Department S4058(1 DATE COMMENTS 11:00 AM AN INSpectume as Cerro Wire + Cable Co. Those attending included Schaeffer , NCDA. De Costanza NYSDEC, BUS J-Schechter, NCDH, BWWM Sarino, Chemist, Cerro Wire inspection revealed That contaminated (oil soaked) had been removed from Various locations on property. Waste containing drums had been relocate on To peur Days segregated into: cooling nil (water soluble) (VMP NapTha) + comide plating studges CN) waste o's have from The area. The copper oxide is still located The privad area used for drying This scale That accumulates from The rolling prokelis. Sewas continues To overflow from The santage system. HEADER FARMER H. Scharffer + This writer net with N. Latten TO Liscuss The removal of wastes of connection of The sanitary system to The N.C. Sewersystem. Mr. Latter state() thoy 1 waste oils have been removed EH 109a 1768

DH-1198, 9/71

Owner or
HEALTH
Continuation Sheet
Nassau County Health Department

C. O. M. M. E. N. T. S.

DATE	COMMENTS
	2) DPW has been contacted + an application
	Filed to connect The sanitary system (That
	has failed To The county select. Mr. Latt-en
	was advised that D.P.W. be contacted +
	informed that the failed tever represents
	an everyoney action. This should expedite
	matters.
	3 Mr. Latten has inventorized all wastes on
	hand, waste Thinners will wo longer be
	produced as The Thinner is now being
	regicted into fresh paint batches. Mr-Latten
	Thornked The county for bring This problem to
	his attention, as he has bow saved his from
	costs initolical in purchasing + removing solvents
	There remains ~ 65 drums of watte
	plating solutions (cyanide bearing wastes),
	30 - auste cooling oils - U65 waste
·	Thinners. Drums previously uncovered have
	been supplied with plastid sheeting covers.
	Mr. Latter is negotiating with several
	scavenger firms for amoual of waste
	materials, including Chemical Management Inc.
	In approximately one month all write drums
	will be removed from siTe.
	6 Cerro is considering in oil-water separator
	for acovery of waste oils.
·	60 Oily sand removed from The site was
EH 109a DH-1198.9/71	1/68
-11-1130, 8//]	

	ONMENTAL	Owner or Inspector
HEALT.Continua	n Ition Sheet	Agent : Address:
The second secon	County Health Department	
DATE		COMMENTS
	Transported 18	
	[Suggest McMC	The T.N.H. Landfill by Cerro. O TO NYSDEC- LAPROND REGARDING
	UE RIFICATION	of THIS?
		•
	· .	1 Schechles
		·
-		
		•
		·
EH 1098 DH-1198.9/7		